Robinson Auto Body

10518 Joshua Oval
Sugar Land, TX
Phone 281-555-9973

Repair Estimate

Estimate number:	EST-630064
Estimate date:	05/16/2025
Customer:	Evelyn Ochoa
Phone:	713-555-0817
Insurance claim:	C-1261
Vehicle:	2024 Kia Sorento
VIN:	
License plate:	72-O966

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,076.99
Hood panel	1	$1,022.16
Right front door shell	1	$588.47
Body labor	26.8 hrs	$1,825.31
Paint and materials		$1,140.56
TOTAL		$5,653.49