Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-524337
Estimate date:	13 Sep 2024
Customer:	Jerry Bennett
Phone:	
Insurance claim:	C-1275
Vehicle:	2012 Toyota Camry
VIN:	A6YUM73E335H33974
License plate:	261 AGS

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,466.93
Front bumper cover	1	$771.23
Left quarter panel	1	$704.82
Body labor	36.2 hrs	$2,463.00
Paint and materials		$938.20
TOTAL		$6,344.18