Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-419018
Estimate date:	2025-03-10
Customer:	Timothy Johnson
Phone:	281-555-7854
Insurance claim:	C-1317
Vehicle:	2018 Toyota Camry
VIN:	T9E501DZ1XY217509
License plate:	NAA-8484

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$579.16
Right front door shell	1	$555.44
Left quarter panel	1	$444.35
Body labor	13.7 hrs	$933.28
Paint and materials		$596.92
TOTAL		$3,109.15