Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-607812
Estimate date:	2025-03-30
Customer:	Danielle Stokes
Phone:	281-555-6264
Insurance claim:	C-1329
Vehicle:	2011 Toyota Camry
VIN:	AHL9H4CAXMN1L1153
License plate:	219G

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,346.37
Headlamp assembly	1	$1,480.30
Right front door shell	1	$762.60
Body labor	39.9 hrs	$2,714.50
Paint and materials		$1,190.97
TOTAL		$7,494.74