Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-407975
Estimate date:	22 Dec 2024
Customer:	Megan Young
Phone:	713-555-0095
Insurance claim:	C-1336
Vehicle:	2013 Toyota Camry
VIN:	EX5GU4KY2WZGH6143
License plate:	66B•187

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$795.20
Left front fender	1	$844.42
Right front door shell	1	$630.37
Body labor	25.3 hrs	$1,721.78
Paint and materials		$943.61
TOTAL		$4,935.38