Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-823319
Estimate date:	August 21, 2024
Customer:	Ronnie Hale
Phone:	
Insurance claim:	C-1343
Vehicle:	2014 Honda Civic
VIN:	VPH2FSHZ9VYFP8215
License plate:	323-MNE

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$946.20
Left front fender	1	$1,116.44
Front bumper cover	1	$900.71
Body labor	26.6 hrs	$1,810.64
Paint and materials		$1,134.20
TOTAL		$5,908.19