Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-634655
Estimate date:	2024-01-02
Customer:	Sandra Dawson
Phone:	346-555-0472
Insurance claim:	C-1351
Vehicle:	2016 Toyota Camry
VIN:	9C6V5JR53HTYR9953
License plate:	359 6NF

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,854.32
Hood panel	1	$1,662.02
Right front door shell	1	$1,262.12
Body labor	41.0 hrs	$2,786.35
Paint and materials		$1,355.98
TOTAL		$8,920.79