Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-477125
Estimate date:	2023-11-11
Customer:	Kristen Rich
Phone:	832-555-2474
Insurance claim:	C-1380
Vehicle:	2018 Ford F-150
VIN:	K7MX6AWT3HDJT3835
License plate:	6QX3906

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,202.73
Trunk lid	1	$1,553.56
Rear bumper reinforcement	1	$1,095.42
Body labor	46.2 hrs	$3,138.28
Paint and materials		$1,421.46
TOTAL		$8,411.45