Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-266158
Estimate date:	1-14-24
Customer:	Erin Anderson
Phone:	346-555-7074
Insurance claim:	C-1422
Vehicle:	2019 Jeep Cherokee
VIN:	3DKN4ALZXF4H16760
License plate:	7X-ZGIN

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$904.98
Left quarter panel	1	$555.43
Headlamp assembly	1	$649.44
Body labor	24.2 hrs	$1,645.93
Paint and materials		$948.81
TOTAL		$4,704.59