Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-239598
Estimate date:	January 24, 2023
Customer:	Joseph Morris
Phone:	346-555-4583
Insurance claim:	C-1451
Vehicle:	2022 Ford F-150
VIN:	ZYHWH65J3VL888626
License plate:	45T PN3

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$406.48
Rear bumper reinforcement	1	$314.90
Right tail lamp assembly	1	$391.49
Body labor	13.6 hrs	$925.66
Paint and materials		$457.16
TOTAL		$2,495.69