Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-536803
Estimate date:	January 8, 2024
Customer:	Peter Morales
Phone:	
Insurance claim:	C-1463
Vehicle:	2018 Toyota Camry
VIN:	RG3Y1EK90485P5197
License plate:	682 9DG

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$311.42
Right front door shell	1	$238.51
Headlamp assembly	1	$160.57
Body labor	9.2 hrs	$623.39
Paint and materials		$345.33
TOTAL		$1,679.22