Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-778194
Estimate date:	31 Oct 2024
Customer:	Timothy Perez
Phone:	346-555-7600
Insurance claim:	C-1466
Vehicle:	2018 Kia Sorento
VIN:	VMYGM81K9KVD88480
License plate:	560542

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,576.19
Trunk lid	1	$998.14
Left tail lamp assembly	1	$903.52
Body labor	29.5 hrs	$2,005.47
Paint and materials		$1,472.94
TOTAL		$6,956.26