Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-786725
Estimate date:	7-31-24
Customer:	Dennis Hall
Phone:	713-555-4662
Insurance claim:	C-1472
Vehicle:	2022 Jeep Cherokee
VIN:	
License plate:	457923

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$878.94
Right front door shell	1	$753.54
Hood panel	1	$849.63
Body labor	35.4 hrs	$2,404.06
Paint and materials		$1,087.51
TOTAL		$5,973.68