Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

Repair Estimate

Estimate number:	EST-159681
Estimate date:	2023-12-09
Customer:	Daniel Burke
Phone:	832-555-7414
Insurance claim:	C-1474
Vehicle:	2019 Honda Civic
VIN:	BKXVFUWX0KCMK2443
License plate:	872 9657

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$356.27
Hood panel	1	$318.60
Front bumper cover	1	$188.27
Body labor	10.7 hrs	$726.81
Paint and materials		$367.00
TOTAL		$1,956.95