Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-284601
Estimate date:	16 Oct 2023
Customer:	Sarah Oconnor
Phone:	281-555-3608
Insurance claim:	C-1481
Vehicle:	2021 Ford F-150
VIN:	YZZ7D3HS48TZX1638
License plate:	XLC-856

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,381.65
Left quarter panel	1	$1,430.71
Headlamp assembly	1	$684.10
Body labor	42.2 hrs	$2,872.85
Paint and materials		$1,095.03
TOTAL		$7,464.34