Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-429765
Estimate date:	4 Jun 2025
Customer:	Ivan Paul
Phone:	346-555-6112
Insurance claim:	C-1498
Vehicle:	2021 Ford F-150
VIN:	G9ZWEA8316AVE7883
License plate:	LYJ 852

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,100.01
Right front door shell	1	$1,136.60
Hood panel	1	$1,197.08
Body labor	32.3 hrs	$2,193.24
Paint and materials		$1,401.51
TOTAL		$7,028.44