Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-628642
Estimate date:	2024-01-06
Customer:	Shirley Rhodes
Phone:	346-555-2671
Insurance claim:	C-1104
Vehicle:	2016 Nissan Altima
VIN:	YSW24VZ0XSRKE4466
License plate:	9A438

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,263.02
Front bumper cover	1	$791.60
Hood panel	1	$580.03
Body labor	44.5 hrs	$2,136.78
Paint and materials		$876.58
TOTAL		$5,648.01

Appraiser remarks

The vehicle presents with substantial crush and deformation along the driver-side rear quarter panel, rocker area, and rear door, consistent with the side impact described at the intersection. Structural measurements were taken and the damage pattern lines up with the reported collision geometry. Several shallow scratches on the lower door skin appear older than this loss and have been noted separately. The repair plan calls for replacing the rear door and quarter panel, straightening the rocker, and refinishing the affected panels. Labor hours are slightly elevated for the scope of this damage and will be reviewed with the shop. Invoice line items show no repeated charges.