Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-752030
Estimate date:	2023-05-05
Customer:	Ricardo Allen
Phone:	281-555-6381
Insurance claim:	C-1312
Vehicle:	2010 Nissan Altima
VIN:	7JW4GJWL6AS2U1537
License plate:	382 YZE

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$915.61
Left front fender	1	$1,179.61
Headlamp assembly	1	$998.65
Body labor	36.4 hrs	$2,474.92
Paint and materials		$1,413.36
TOTAL		$6,982.15

Appraiser remarks

The vehilce presented with scraping and a dented panel along the right rear quarter, with paint transfer and a cracked side mirror housing, all consistent with a sideswipe while changing lanes. Most of the damage lines up with the impact as described by the owner. The repair plan calls for panel straightening, refinishing of the affetced area, and replacement of the mirror housing, and the labor hours requested fit the scope of that work. The supplied invoices show no repeated charges. No earlier damage to this vehicle is known from the rceords reviewed, so the current repairs are treated as tied to this loss.