Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-627290
Estimate date:	10-12-24
Customer:	Emma Chavez
Phone:	713-555-4380
Insurance claim:	C-1330
Vehicle:	2019 Nissan Altima
VIN:	AR6K90VK7AAMZ0451
License plate:	Y70 8GU

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,524.73
Left front fender	1	$1,227.24
Left quarter panel	1	$713.77
Body labor	34.8 hrs	$2,364.72
Paint and materials		$1,636.93
TOTAL		$7,467.39

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact. The bumper cover, hood leading edge, and both headlamp assemblies show crush and fracture patterns that line up with the described contact point, and the radiator support shows only minor deformation. The repair plan calls for rpelacing the bumper cover and headlamps, straightening the support, and refinishing the hood. The listed labor hours are in line with the work required for this damage. The invoices reviewed show no repeated charges for the same operations. No proir damage to this vehicle is known from the file, and the repair scope is limited to the current loss.