## reminder\_list-1634205598.csv

No.	Nama	Berat	DRC	Jml.	Kondisi	TgI	Tgl
Rak	Petugas	Gulungan	Gulungan	Gulungan	Penyimpanan	Digulung	Diolah
1A.01	Kwarista	25	70	32	baik	14/10/2021	25/10/2021
2.11	sukisman	26	70	110	baik	11/10/2021	22/10/2021
2.12	sukisman	26	70	528	baik	11/10/2021	22/10/2021
lantai ruang pump	sukisman	25	70	68	baik	10/10/2021	21/10/2021
depan ruang 8 single dryer	sukisman	25	70	177	baik	10/10/2021	21/10/2021
2.11	sukisman	25	70	288	baik	09/10/2021	20/10/2021
01 (lantai bak sirkulasi)	sukisman	25	70	180	baik	09/10/2021	20/10/2021
lantai hummer mill III	sukisman	25	70	156	baik	09/10/2021	20/10/2021
lantai cerobong abu	sukisman	25	70	132	baik	09/10/2021	20/10/2021
2.10	sukisman	26	70	288	baik	08/10/2021	19/10/2021
2.11	sukisman	26	70	206	baik	08/10/2021	19/10/2021
01 (dekat lemari alat)	sukisman	26	70	176	baik	08/10/2021	19/10/2021
2.09	sukisman	25	70	120	baik	07/10/2021	18/10/2021
04 (dekat crepper ulang)	sukisman	25	70	139	baik	07/10/2021	18/10/2021
2.10	sukisman	25	70	216	baik	07/10/2021	18/10/2021
2.03 - 2.04	sukisman	25	70	216	baik	07/10/2021	18/10/2021
1A.12	abdul	26	70	70	baik	06/10/2021	17/10/2021
2.08	Sukisman	25	70	348	baik	06/10/2021	17/10/2021
2.09	Sukisma	25	70	456	baik	06/10/2021	17/10/2021
06 (depan bak cutter)	abdul	25	70	170	baik	06/10/2021	17/10/2021
1.07	abdul	26	70	500	baik	06/10/2021	17/10/2021
1B.12	abdul	26	70	72	baik	06/10/2021	17/10/2021
2.08	Sukisman	26	70	156	baik	05/10/2021	16/10/2021
2.01	Abdul	26	70	235	baik	05/10/2021	16/10/2021
2.02	Abdul	26	70	235	baik	05/10/2021	16/10/2021
2.07	Sukisman	26	70	492	baik	05/10/2021	16/10/2021