

CSIDC Land Sentinel

Official Compliance Audit Report

Project ID: TEST-PDF-001

Plot Name: Test Project

Area ID: PLOT-123

Date Scanned: 2026-02-14

STATUS: VIOLATION DETECTED (Score: 45/100)

Reference Layout

Satellite Analysis

[Reference Missing]

[Analysis Missing]

Detailed Metrics

Total Valid Area (sqm)	5000
Encroached Area (sqm)	155.0 (Est.)
Deviation Percentage	15.5%

AI Recommendations

- Check permit
- Issue notice

Authorized Signatory
CSIDC Nodal Officer