Invoice Draft

Entirely fictional commercial repair example. Not a completed Westline client job. Verified details refer only to evidence within this demonstration.

JOB 001 / UNIT 2184

Complaint	Trailer air leak
Status	Repair completed; documentation review pending
Technician notes	Fictional technician reports an audible leak at a trailer air-line fitting. Replaced the damaged fitting and checked the connection.
Verified repair details	In this fictional record, the technician reports no leak at the repaired connection during a soap-solution check. No roadworthiness certification or full brake-system test is represented.
Pending approvals	Client review of labor, parts and final invoice remains pending.
Next action	Review the service notes and supplied time record before approving the invoice.
Responsible party	Client repair manager: repair acceptance. Client billing reviewer: final invoice.
Time records	Illustrative shift, local client time: arrival 22:10; work 22:20–23:05 (45 minutes); departure 23:15. Travel time not supplied.
Invoice review status	Awaiting client review. No approved rates or parts price supplied; no amount due calculated.

DRAFT - NOT FOR PAYMENT

Labor: 45 minutes x client-approved rate. Rate not supplied.
Replacement fitting: quantity 1. Price not supplied.
Travel, call-out fees and tax: client review required.
No total calculated. Client billing reviewer must confirm rates, parts, tax and authorization before issue.

Repair acceptance and financial approval remain with the client. No roadworthiness certification, billable total or approval is implied.