

PARTS OPERATION STANDARDS - POS Audit Score								
Distributor name		ANGOLAUTO	Audit date:		8/26/2019			
Distributor code		8167	Audit done by:		Nutan			
Location		NULL	Last date of Audit:		28/07/2020 12:00:00 AM			
Distributor representatives			Last Audit by:		Amit Goyal			
			Last Audit Score:		0%			
					POS Audit Score		0%	
Sr	POS Process name	Enablers(%)			Results(%)			Total
		Max Marks	Score	% Score	Max Marks	Score	% Score	
1	Warehouse Management	225	0	0	75	0	0	0%
1	Inventory Management	55	0	0	110	0	0	0%
1	Parts Ordering	50	0	0	50	0	0	0%
1	Parts Operations	30	0	0	20	0	0	0%
1	Genuine Parts Operations	70	0	0	30	0	0	0%
1	Genuine Accessories	105	0	0	25	0	0	0%
1	Parts Pricing	35	0	0	40	0	0	0%
1	Retail Outlet	50	0	0	0	0	0	0%
1	SCAN	20	0	0	0	0	0	0%
1	Manpower Roles & Responsibilities	50	0	0	0	0	0	0%
POS Adherence level		690	0	0%	350	0	0%	82%