

Arista PE Bangalore KA-76 ALARM_1233 SOP

Node: Arista-PE-Bangalore-KA-76 | **Vendor:** Arista | **Severity:** Warning | **Alarm Code:** ALARM_1233

Description

This SOP is for resolving the ALARM_1233 (Warning) on Node ID: Arista-PE-Bangalore-KA-76, a Provider Edge Router manufactured by Arista.

Potential Root Causes

Cause	Probability
High CPU utilization due to BGP prefix filtering	High
Misconfigured BGP neighbor	Medium
Hardware failure in the router	Low

Diagnostic Commands

```
show system resources
show bgp summary
show bgp neighbors
debug bgp
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization using show system resources', 'Action': 'Execute the command "show system resources" to verify CPU utilization'}
- Step 2: {'Step': 'Verify BGP neighbor configuration', 'Action': 'Execute the command "show bgp neighbors" to verify BGP neighbor configuration'}
- Step 3: {'Step': 'Clear BGP session', 'Action': 'Execute the command "clear bgp *" to clear the BGP session'}
- Step 4: {'Step': 'Verify BGP prefix filtering', 'Action': 'Execute the command "show ip bgp filter-list" to verify BGP prefix filtering'}
- Step 5: {'Step': 'Replace faulty hardware (if applicable)', 'Action': 'Execute the command "no shutdown" to enable the interface'}

Post-Check Verification

```
show bgp summary
show bgp neighbors
```

```
show ip bgp filter-list  
show system resources
```