

```
1  {
2    "image": {
3      "filename": "vehicle_001234.jpg",
4      "width": 1920,
5      "height": 1080,
6      "timestamp": "2025-05-20T16:12:00Z",
7      "image_type": "RGB"
8    },
9    "objects": [
10     {
11       "id": "veh_001",
12       "type": "vehicle",
13       "bbox": [400, 300, 800, 650],
14       "view_pose": "rear",
15       "direction": "northbound",
16       "vehicle_info": {
17         "category": "Heavy Vehicle",
18         "subcategory": "Prime Mover",
19         "country": "MY",
20         "brand": "Volvo",
21         "model": "FMX",
22         "color": "White",
23         "operator": "DHL",
24         "number_of_seats": 2
25       },
26       "mechanical": {
27         "number_of_wheels_visible": 10,
28         "number_of_axles_inferred": 5,
29         "number_of_axles_raised": 1,
30         "truck_trailer_labels_visible": true,
31         "cargo_present": false
32       },
33       "attributes": {
34         "is_taxi": false,
35         "is_bus": false,
36         "bus_type": "",
37         "is_emergency_vehicle": false,
38         "is_electric": false
39       },
40       "license_plate": {
41         "bbox": [700, 620, 780, 640],
42         "text": "WXD1023",
43         "country": "MY",
44         "format": "standard",
45         "blurred": false,
46         "visible": true
47       },
48       "wheels": [
49         {
50           "id": "wheel_001",
51           "type": "doubleWheel",
52           "bbox": [420, 610, 440, 640]
53         },
54         {
55           "id": "wheel_002",
56           "type": "doubleWheel",
57           "bbox": [460, 610, 480, 640]
58         },
59         {
60           "id": "wheel_003",
61           "type": "doubleWheel",
62           "bbox": [700, 610, 720, 640]
63         }
64       ],
65       "axles": [
66         {
67           "id": "axle_001",
68           "bbox": [410, 600, 490, 650],
69           "wheel_ids": ["wheel_001", "wheel_002"],
```

```

70         "raised": false
71     },
72     {
73         "id": "axle_002",
74         "bbox": [690, 600, 770, 650],
75         "wheel_ids": ["wheel_003"],
76         "raised": true
77     }
78 ],
79 "attachments": [
80     {
81         "id": "attach_001",
82         "type": "trailer",
83         "subtype": "box",
84         "bbox": [820, 300, 1600, 650],
85         "has_license_plate": true,
86         "license_plate": {
87             "text": "TRL9087",
88             "bbox": [1550, 620, 1600, 640],
89             "country": "MY",
90             "blurred": false,
91             "visible": true
92         },
93         "cargo_present": true
94     }
95 ],
96 "CoT": [
97     "Volvo prime mover detected pulling a box-type trailer.",
98     "Main vehicle plate WXD1023 and trailer plate TRL9087 are both visible.",
99     "Total of 10 wheels seen; one axle appears lifted.",
100     "Trailer is loaded (cargo flag = true).",
101     "No bus, taxi, or emergency markings detected."
102 ]
103 }
104 ]
105 }
106

```