ProcessStep

step_id	step_name	process_group
1	산화막 증착	Deposition
2	식각 공정	Etch
3	세정 공정	Cleaning
4	검사 공정	Inspection

Lot

lot_id	product_name	wafer_qty	lot_status
L001	DRAM-A	25	processing
L002	DRAM-A	25	completed
L003	NAND-B	25	warning

Equipment

equipment_id	model_name	equipment_type	status
101	CVD-B200	Deposition	active
102	ETCH-A100	Etch	active
103	CLEAN-D300	Cleaning	active
104	INSPECT-E500	Inspection	active

Sensor

sensor_id	equipment_id	sensor_name	unit	normal_min	normal_max
1	101	chamber_temp	C	390.00	410.00
2	101	chamber_pressure	Torr	1.80	2.20
3	102	rf_power	W	480.00	520.00
4	102	gas_flow	sccm	95.00	105.00
5	103	cleaning_flow	L/min	18.00	22.00
6	103	chemical_temp	C	23.00	27.00
7	104	defect_count	count	0.00	5.00
8	104	inspection_temp	C	22.00	28.00

SensorMeasurement

measurement_id	run_id	sensor_id	measured_at	measured_value
1	1	1	2024-03-15 09:05:00	398.00
2	1	1	2024-03-15 09:15:00	402.00
3	1	1	2024-03-15 09:25:00	405.00
4	1	2	2024-03-15 09:05:00	1.95
5	1	2	2024-03-15 09:15:00	2.00
6	1	2	2024-03-15 09:25:00	2.05
7	2	3	2024-03-15 10:05:00	500.00
8	2	3	2024-03-15 10:15:00	508.00

RunHistory

run_id	lot_id	equipment_id	step_id	start_time	end_time	run_status
1	L001	101	1	2024-03-15 09:00:00	2024-03-15 09:30:00	completed
2	L001	102	2	2024-03-15 10:00:00	2024-03-15 10:25:00	completed
3	L001	103	3	2024-03-15 10:40:00	2024-03-15 10:55:00	completed
4	L002	101	1	2024-03-15 11:10:00	2024-03-15 11:45:00	completed
5	L002	102	2	2024-03-15 12:10:00	2024-03-15 12:35:00	completed
6	L002	104	4	2024-03-15 13:00:00	2024-03-15 13:20:00	completed
7	L003	101	1	2024-03-15 14:00:00	2024-03-15 14:35:00	warning
8	L003	102	2	2024-03-15 15:00:00	2024-03-15 15:30:00	warning