



SERVICE REPORT

Customer Details

SAKIB AL HASSAN
Dhaka
Mobile No:
000000000

Complaint Details

Job No: CMP-000041
Book Date & Time: 21
Sept 2026, 02:19 pm
Service Engineer:
Service-Engineer
Job Status: Completed
Solve Date & Time: 22
Sept 2026, 12:10 am

Product Details
Google Tank

Model Number
SJDHFSKDFSD

Call Type
Break Down

Problem / Work Reported
NOT WORKING

Actual Issue
RF PCB Problem

Corrective Action
PCB Changed


Call Closure Details

Sr No.	Spare Part Description	Quantity
No spare parts used		

Payment Details

Approximate Cost: Rs.
435345

Picture of Work



Work Done : PCB Changed

TERMS & CONDITIONS

- 1. Payment Terms: The client shall pay the service provider within [insert timeframe, e.g., 30 days] from the date of invoice.
- 2. Scope of Work: The service provider agrees to perform the work described in the job sheet, and the client agrees to pay for the services rendered.
- 3. Warranty and Liability: The service provider offers a 30 Days Warranty.
- 4. Spares comes with 30 Days Warranty.
- 5. Material Once sold will not be taken back.



Customer Signature

SALES : | CUSTOMER SUPPORT : 019783453545

This is computer generated Service Report and does not require any signature.
Service CRM