

# Plant\_1\_Equipments

id	tag	name	is_working	remark	plant_id
1	FE-01	Fire Extinguisher	1	Good Pressure	1
2	FE-02	Fire Extinguisher	1	Loose hose	1
4	IV-02	Isolation Valve	0		1