

New Work Order

Order #TVO-700000520

Dear Installer,

Thank you for accepting Tyres Vision Work Order #TVO-7000000520

Please find the details below:

Customer Details

Daniel Nedumannil Chacko

Vehicle Information

Plate No.: A/61182 Make: Hyundai

Model: Tucson Year: 2013

Order Updates

Delivery Date/Time: 22-02-25 07:00pm

Installer Information

Safeer Tyres - Ajman

Al Jurf, Industrial Area - 1, Sheikh Ammar Bin

Humaid St Aiman

United Arab Emirates

Customer will come tomorrow at 7pm for the fitting customer will make online payment to tyrevision

ITEM QTY

Goodyear 225/60 R17 99V Wrangler Triplemax 2021

4

Please note the following,

- 1. The tyres supplied to you under this work order must be fitted ONLY to the Vehicle bearing the license plate number and description specified here. Please contact us if the customer insists on fitting these to another vehicle.
- 2. Please refuse to accept delivery if the tyres being delivered by the courier are not the exact same specifications and DOT as listed here
- 3. The customer has paid for new tyres, delivery, installation, balancing and disposal of old tyres. You will have to charges the customer directly for Alignment or any other service you provide.
- 4. The work order will not be considered complete unless the customer sign this work order and you email back a scanned copy to your Tyres Vision contact.

Please feel free to call us a	or Write to us at customercare@t	yresvision.com	

Job Complete (Y/N):	Remarks (if any):
Date & Time:	Customer Signature: