



## New Work Order

**Order #TVO-7000000874**

Dear Installer,

Thank you for accepting Tyres Vision Work Order #TVO-7000000874

Please find the details below :

### Customer Details

Sahbi Baccouche

### Vehicle Information

Plate No.: X38747

Make: Ford

Model: Explorer

Year: 2016

### Installer Information

Star Tyre Services

Near Amber Garden Furniture, D63 Road

Dubai

United Arab Emirates

**Delivery Date/Time :** 22-04-23 10:00am

### Order Updates

Tire fitting at 10:30AM tomorrow --customer will pay online

ITEM	QTY
Kumho 245/60 R18 105V Crugen HP91 2022	3

### Please note the following,

1. The tyres supplied to you under this work order must be fitted ONLY to the Vehicle bearing the license plate number and description specified here. Please contact us if the customer insists on fitting these to another vehicle.
2. Please refuse to accept delivery if the tyres being delivered by the courier are not the exact same specifications and DOT as listed here
3. The customer has paid for new tyres, delivery, installation, balancing and disposal of old tyres. You will have to charges the customer directly for Alignment or any other service you provide.
4. The work order will not be considered complete unless the customer sign this work order and you email back a scanned copy to your Tyres Vision contact.

Please feel free to call us at or Write to us at [customercare@tyresvision.com](mailto:customercare@tyresvision.com)

Job Complete (Y/N):\_\_\_\_\_

Remarks (if any):\_\_\_\_\_

Date & Time:\_\_\_\_\_

Customer Signature:\_\_\_\_\_