



DESCRIPTION-
Drg. No-

ASSY.PROP.SHAFTS 490L JT 570 F

Shift
Mode No-

B

RSB TRANSMISSIONS (I) LTD , LUCKNOW

Part No:-

Invoice No.
5 Supply Date

FC320400

18/12/2024

SR NO.	Characteristics	Specification	Mode Of Checking.	1	2	3	4	5	Product Status	Remark
1	Tube Length	As per Control Plan	Measuring Tape	570	5701	5702	5704	5702	All Shaft Found of ok	Checked in process/poka yoke Control
2	Matching of Tube Length in QR Code Sticker &	Match tube lengh with QR Sticket	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
3	QR Code Sticker Proper Scanning	Checked Part Number ,Drawing Modification no	Barcode/ QR Code Scanner	FC320400	FC3204001	FC3204002	FC3204004	FC3204005	All Shaft Found of ok	
4	Total Flange to Flange Length In Closed	As per Control Plan	Measuring Tape	895±2	895±21	895±21	895±23	895±21	All Shaft Found of ok	Checked in process/poka yoke Control
5	Type of Centre Bearing Kit	As per Control Plan	Visual	2518 KIT	2518 KIT	2518 KIT	2518 KIT	2518 KIT	All Shaft Found of ok	
6	Rotary Movment Of Centre Bearing Kit	No jamming of center Brg.Rotation	Hand Feel	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
7	Coupling Flange Orientations (As per QA Alert)	As per Control Plan (checked Mounting hole	Visual	90°	90°	90°	90°	90°	All Shaft Found of ok	
8	UJ Movement (Smooth)	Proper And Equal Free ness	Hand Feel	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
9	Circlip Seating/ Circlip Missing	No circlip missing ,proper setting and no crack	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
10	Paint Missing at Slip Area & UJ Area.	No paint missing at uj Area	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
11	Paint Condition	(No Run Down/Blisters/Patches,No paint allow in	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
12	Anti Rust Oil @ Machining Area	No anti rust oil missing in maching Area	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
13	Locking of Cheknuts	Hex Nut luck by punching	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
14	Proper Adhesion on Painted Surface (4B)	No Paint peel off Allow On Prop Shaft	Visual (As Per Standard)	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
15	Rust free	No Rust allow on prop shaft	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
16	No Welding Defect	No Blow hole ,porosity ,spatter ,under cut allow)	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
17	Proper Seating of Balancing Weight Condition On	proper setting	Visual Checked By hammer	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
18	Grease Nipple Condition & Status	No free ness and loose	Visual	NON GREASABLE	NON GREASABLE	NON GREASABLE	NON GREASABLE	NON GREASABLE	All Shaft Found of ok	
19	Mounting Hole Centre Distances	As per control plan	Vernier/ Checking Fixture	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	As per control plan
20	Mounting hole ID	As per control plan	Checking Pin /Round plug Gauge	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	As per control plan
21	Drill Hole (4 nos)	As per control plan	Checking Pin /Round plug Gauge	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	Incoming control (Checked on Sampling plan)
22	PCD	As per control plan	Checking Fixture	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	Incoming control (Checked on Sampling plan)
23	Tube OD	As per control pla	Vernier /snap gauge	Ø101.57X3.41	Ø101.57X3.41	Ø101.57X3.41	Ø101.57X3.41	Ø101.57X3.41	All Shaft Found of ok	Incoming control (Checked on Sampling plan)
24	Deadener available	AS per control plan	sound detect	No	No	No	No	No	All Shaft Found of ok	

Remarks :- (IF ANY)
CHECKED BY (SIGNTAURE):-
FORM NO :

Date
18/12/2024

PASSED DISPATCH (SIGNATURE): SUDHIR