

AHON FloodWatch

Barangay Tonsuya | Administrator Telemetry Report

Generated	2026-09-24 17:25:17	Generated by	admin
-----------	---------------------	--------------	-------

Executive summary

512.00 cm	Danger	2	2	9 / 2
As of 2026-09-24 16:57:13	Normal / Warning / Critical	Current active events	Status = active	Last 24 hours

Threshold reference

Normal / Low	Warning / Moderate	Critical / High
Safe or optimal operating range	Needs monitoring and verification	Immediate action required

Telemetry history

Timestamp	Level	Status	Sensor	GSM
2026-09-24 16:57:13	512.00 cm	Danger	online	connected
2026-09-24 16:52:49	1023.00 cm	Danger	online	connected
2026-09-24 16:52:20	1023.00 cm	Danger	online	connected
2026-09-24 16:52:03	1023.00 cm	Danger	online	connected
2026-09-24 16:51:30	450.00 cm	Danger	online	connected
2026-09-24 16:34:48	123.00 cm	Normal	online	connected
2026-09-24 16:01:57	15.50 cm	Normal	online	connected
2026-09-23 21:49:48	15.50 cm	Normal	online	connected

Status distribution

Normal 3	Alert 0	Warning 0	Danger 5
----------	---------	-----------	----------

This report contains recorded telemetry only. Operational decisions remain with the authorized barangay administrator.