

INTERVENTION REPORT

JOB NO.
INTERVENTION NO.
002502
DATE
14/05/2026
CUSTOMER INFORMATION

Name	CELESTO RICHIE TONE	Contact Person	Mrs. Charitha Venkama
Address		Telephone No	Fax
		Email Address	

JOB CATEGORY (Please Tick Appropriate Box)

Installation	Start Up & Commissioning	Outdoor Repair	☒	Workshop Repair	Servicing	Maintenance Contract	Survey	Others
--------------	--------------------------	----------------	-------------------------------------	-----------------	-----------	----------------------	--------	--------

EQUIPMENT / SYSTEM

Equipment	Fire Alarm Panel	Make		Model	
Date Installed		Serial No.			

NATURE OF INTERVENTION / FAULT REPORTED

(1) Faults on Fire Panel Screen Display

ACTION TAKEN / WORK DONE

(a) Replace faulty detectors (Smoke) 10 26 & 10 27 located on 1st floor

(b) Replace batteries inside panel (x2)

(c) clear faults & reset & test panel

Technician(s) Involved		Work Completed	YES	☒	NO
Time In	Andrew	Please give details if NO			
Time Out	1200				
Duration of Intervention	1730				

FOR OFFICE USE

Equipment Under Warranty								
YES	NO	D.N						

TECHNICIAN'S REPORT

(A) Faults clearing done and panel tested

→ Servicing of whole installation, all detectors, break glass and alarm will be serviced next week

COMMENTS / RECOMMENDATIONS
FOR THE CUSTOMER

Name	Charitha Venkama
Job Title	ICM
Signature	Charitha
Date	14/05/2026

FOR TECHNET ENGINEERING LTD

Name	Yashna Rutch
Job Title	
Signature	
Date	14/05/2026

ANY COMPLAINTS SHOULD BE MADE WITHIN 24 HOURS

SURVEY AND DIAGNOSIS IS BILLABLE - AN INVOICE WILL BE SENT AFTER THE INTERVENTION