

MIGNOGNA COLLISION CENTER
200 MIGNOGNA LANE, GREENSBURG, PA 15601
Phone: (724) 838-0444
FAX: (724) 838-0449

Workfile ID: c428e040
Federal ID: 251791430

Estimate of Record

Customer: STONE, BRANDEN

Written By: Troy Pocky, 5/23/2014 12:43:27 PM
Adjuster: Mcqueen, Maryann, (800) 531-8722 Business

Insured:	STONE, BRANDEN	Policy #:	012448161	Claim #:	012448161000000009001
Type of Loss:	Collision	Date of Loss:	5/22/2014 12:00:00 PM	Days to Repair:	2
Point of Impact:	16 Non-Collision				

Owner:	Inspection Location:	Insurance Company:
STONE, BRANDEN	UNKNOWN	USAA
44 ARNETT RD	Other	NORFOLK 1501
RHINEBECK, NY 12572		VISIT US AT USAA.COM OR CALL..
(785) 813-1206 Evening		(800) 531-8722 Business
(785) 813-1206 Cell		

VEHICLE

Year:	2010	Body Style:	4D VAN	VIN:	5TDYK4CC5AS300206	Mileage In:	112851
Make:	TOYO	Engine:	6-3.5L-FI	License:	GDD7313	Mileage Out:	
Model:	SIENNA 4X2 XLE	Production Date:	6/2009	State:	NY	Vehicle Out:	
Color:	White DIAMOND Int:	Condition:	Good	Job #:			

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

Dual Mirrors
Body Side Moldings
Privacy Glass

Console/Storage
Overhead Console
Wood Interior Trim

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Dual Air Condition

Dual Power Sliding Doors
Home Link

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Auxiliary Audio Connection
CD Changer/Stacker

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control

Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
3rd Row Seat
Retractable Seats
Captain Chairs (2)

WHEELS

Aluminum/Alloy Wheels

PAINT

Three Stage Paint

Estimate of Record

Customer: STONE, BRANDEN

Vehicle: 2010 TOYO SIENNA 4X2 XLE 4D VAN 6-3.5L-FI White DIAMOND

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		LIFT GATE					
2	R&I	R&I liftgate assy				1.2	
3	*	Rpr Lift gate w/o power door, w/monitor w/o spoiler				<u>6.0</u>	2.3
4		Add for Three Stage					1.6
5		Add for Inside					0.5
6	*	R&I Molding assy w/monitor pearl white				<u>0.3</u>	
7	**	Subl <u>A/M Glass w/solar, gray privacy tint w/hardware plus kit</u>		1	<u>158.15</u> T		
8	*	Subl <u>Glass w/solar, gray privacy tint w/hardware Labor</u>		1	<u>116.00</u> T		
9	R&I	Wiper arm				0.2	
10	R&I	Spoiler				0.7	
11	R&I	Lift gate trim stone				0.3	
12	R&I	Window trim center, w/power rear seat stone				0.2	
13	R&I	RT Window trim side, w/power door stone				0.2	
14	R&I	LT Window trim side, w/power door stone				0.2	
15	*	Rpr <u>LT Actuator REPAIR BRACKET</u>				<u>0.5</u>	
16	R&I	Weatherstrip				0.5	
17		REAR LAMPS					
18	R&I	RT Combo lamp assy				0.3	
19	R&I	LT Combo lamp assy				0.3	
20	#	Refn CORROSION PROTECTION					0.3
21	**	Repl A/M CAR COVER		1	3.00	0.2	
22	**	Repl A/M HAZARDOUS WASTE REMOVAL		1	3.50		
SUBTOTALS					280.65	11.1	4.7

NOTES

Estimate Notes:

DR=5/22/14

DC=5/22/14

DI=5/23/14

ERT=3

VEHICLE OWNER WAS PROVIDED A COPY OF THE DAMAGE REPORT PRIOR TO REPAIRS

CALL USAA for supplement approval 800-531-USAA x 7-9572, and FORWARD SUPPLEMENT via email norpd@usaa.com or fax to 703-740-9431.

Please include the USAA claim number on every correspondence.

Prior Damage Notes:

NONE

Estimate of Record

Customer: STONE, BRANDEN

Vehicle: 2010 TOYO SIENNA 4X2 XLE 4D VAN 6-3.5L-FI White DIAMOND

ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					164.65
Body Labor	11.1 hrs	@		\$ 48.00 /hr	532.80
Paint Labor	4.7 hrs	@		\$ 48.00 /hr	225.60
Paint Supplies	4.7 hrs	@		\$ 27.00 /hr	126.90
Miscellaneous					116.00
Subtotal					1,165.95
Sales Tax	\$ 1,165.95	@		6.0000 %	69.96
Grand Total					1,235.91
Deductible					250.00
CUSTOMER PAY					250.00
INSURANCE PAY					985.91

PLEASE NOTE: POSSIBLE ADDITIONAL HIDDEN DAMAGE MAY BE FOUND UPON VEHICLE DISASSEMBLY.

Please Present A Copy Of This Estimate To A Repair Facility Of Your Choice

*USAA Subsidiaries include: United Services Automobile Association(USAA), USAA Casualty Insurance Company(CIC), USAA General Indemnity Company(GIC) USAA County Mutual Insurance(CMI) and Garrison Property Casualty Insurance Company. Garrison Property and Casualty Insurance Company, a subsidiary of USAA Casualty Insurance Company, is authorized to use the USAA logo, a registered trademark of United Services Automobile Association.

This is not an authorization to repair. Failing to present this estimate to the repairing garage before repair may result in additional expenses to you. A USAA appraiser must authorize any supplement to this estimate. Repairs to this vehicle may require specific welding equipment as recommended by the manufacturer.

If alternative quality replacement parts have been included in this appraisal, the source for these parts has also been disclosed. If alternative quality replacement parts as listed on the appraisal are ultimately used in the repair of your vehicle, the warranty on such parts will be equal to, or greater than, the parts being replaced, as stated in USAA's limited parts warranty. USAA warrants that the parts used on your vehicle will be of like kind and quality, function, fit, safety and corrosion protection as the part or parts they replace. USAA identifies certified and validated parts for sheet metal replacement parts.

Estimate of Record

Customer: STONE, BRANDEN

Vehicle: 2010 TOYO SIENNA 4X2 XLE 4D VAN 6-3.5L-FI White DIAMOND

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD ANY INSURANCE COMPANY OR OTHER PERSON FILES AN APPLICATION FOR COMMERCIAL INSURANCE OR A STATEMENT OF CLAIM FOR ANY COMMERCIAL OR PERSONAL INSURANCE BENEFITS CONTAINING ANY MATERIALLY FALSE INFORMATION, OR CONCEALS FOR THE PURPOSE OF MISLEADING, INFORMATION CONCERNING ANY FACT MATERIAL THERETO, AND ANY PERSON WHO, IN CONNECTION WITH SUCH APPLICATION OR CLAIM, KNOWINGLY MAKES OR KNOWINGLY ASSISTS, ABETS, SOLICITS OR CONSPIRES WITH ANOTHER TO MAKE A FALSE REPORT OF THE THEFT, DESTRUCTION, DAMAGE OR CONVERSION OF ANY MOTOR VEHICLE TO A LAW ENFORCEMENT AGENCY, THE DEPARTMENT OF MOTOR VEHICLES OR AN INSURANCE COMPANY, COMMITS A FRAUDULENT INSURANCE ACT, WHICH IS A CRIME, AND SHALL ALSO BE SUBJECT TO A CIVIL PENALTY NOT TO EXCEED FIVE THOUSAND DOLLARS AND THE VALUE OF THE SUBJECT MOTOR VEHICLE OR STATED CLAIM FOR EACH VIOLATION.

You are entitled to the return of all replaced parts, except warranty and exchange parts, but you must ask for them in writing before any work is done. If you authorize work by phone, the shop must keep any replaced parts, and make them available when you pick up the vehicle.

The glass part price, kit and labor has been calculated by USAA's Glass Administrator, Safelite Auto Glass based on market pricing for your area. Please call Safelite at 1-800-826-0914 to arrange for the work to be completed for the cost listed on this estimate.

Customer: STONE, BRANDEN

Vehicle: 2010 TOYO SIENNA 4X2 XLE 4D VAN 6-3.5L-FI White DIAMOND

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide ARM8530, CCC Data Date 5/14/2014, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM or A/M. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2014 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Estimate of Record

Customer: STONE, BRANDEN

Vehicle: 2010 TOYO SIENNA 4X2 XLE 4D VAN 6-3.5L-FI White DIAMOND

ALTERNATE PARTS USAGE

Year: 2010 Body Style: 4D VAN VIN: 5TDYK4CC5AS300206 Mileage In: 112851
Make: TOYO Engine: 6-3.5L-FI License: GDD7313 Mileage Out:
Model: SIENNA 4X2 XLE Production Date: 6/2009 State: NY Vehicle Out:
Color: White DIAMOND Int: Condition: Good Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	0	3
Optional OEM	Automatically List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	0	0