Lab 2.2 source pack

All records are fictional training data. They describe no actual facility, person or organisation. Values are teaching assumptions, not approved design criteria. Do not use outputs to operate, maintain or approve real equipment.

site-notes.txt

INS-04 revision 1 | fictional 2026-08-17 inspection
09:10 P-101 running; flow display 48 m3/h. 09:12 display 32 m3/h; timestamp photo not available. 09:15 gauge 3.1 bar. 09:20 display 47 m3/h. Guard visually present; integrity not verified. Minor liquid on floor near coupling; identity unknown. No injury reported. Maintenance person suggests seal leak, not confirmed. Calibration sticker unreadable. Permit record not supplied. No inspection of energised internals occurred. Missing: suction reading, sensor calibration evidence, work order, sample identification.

report-template.md

Weekly engineering progress report
Reporting period | Author | Version | Draft status
Executive summary
Completed work with evidence
Open actions and owners
Risks and blockers
Decisions required
Next period plan
Sources and unresolved assumptions
Reviewer and release decision