

SOLAR PANEL INSPECTION REPORT

Batch ID: 171 | Date: 2026-05-27 10:42

Summary Statistics:

- Total Panels Scanned: 57
- Defective Panels Found: 7
- Health Rate: 87.72%

Critical Defects List (Action Required):

Panel ID	Defect Type	Efficiency Loss	Image Source
R03_C02	crack	600.0%	DJI_0953.JPG
R02_C01	crack	600.0%	DJI_0955.JPG
R02_C02	hotspot_multi_cell	200.0%	DJI_0957.JPG
R02_C02	hotspot_single_cell	600.0%	DJI_0959.JPG
R02_C03	hotspot_single_cell	600.0%	DJI_0959.JPG
R02_C02	hotspot_single_cell	600.0%	DJI_0961.JPG
R02_C03	hotspot_single_cell	600.0%	DJI_0961.JPG