

EPC SOLAR
Clean Energy Professional

SOLAR AI INSPECTION REPORT

AUTOMATED PV ANOMALY DETECTION & DIAGNOSIS

Project Name:	Solar PV Inspection Project
Location:	Unspecified Location
Scan Date/Time:	2026-06-05 17:30:18
Scan Agency:	EPC Solar Operational Engineering Team
Drone Device:	DJI Matrice 300 RTK + Zenmuse H20T
Scan Scope:	Unspecified Scope
Panel Capacity:	600.0 W

1. Executive Summary

TOTAL SCANNED PANELS

349

Healthy: 338 (96.8%)

ANOMALOUS / FAULTY PANELS

11

Fault Rate: 3.2%

TOTAL ESTIMATED POWER LOSS

2.4 kW

Average Loss: 218.2 W / fault

OVERALL SYSTEM HEALTH TIER

Tier A (Excellent)

Based on total healthy panel ratio

2. Defect Type Distribution Analysis

Defect Class	English Term	Count	Ratio (%)
Diem nong don cell	Single Hotspot	24	100.0%
Diem nong da cell	Multi Hotspot	0	0.0%
Bong che khuat	Shading	0	0.0%
Bam bui ban	Soiling	0	0.0%
Nut vo vat ly	Crack	0	0.0%

3. Detailed PV Anomalies Log

Anomalous Panel R02_C06 (Row 2, Col 6) | GPS: 10.8234, 106.6312

Defects Found: Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 46.4%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: middle-left (u:0.19, v:0.54)
Raw Thermal Image: DJI_0843_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R06_C04 (Row 6, Col 4) | GPS: 10.824, 106.6307

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 38.0%, 30.7%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-center (u:0.54, v:0.24), upper-left (u:0.15, v:0.2)
Raw Thermal Image: DJI_0843_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R05_C06 (Row 5, Col 6) | GPS: 10.82385, 106.6312

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 49.9%, 34.6%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-right (u:0.78, v:0.28), upper-left (u:0.14, v:0.18)
Raw Thermal Image: DJI_0843_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R04_C07 (Row 4, Col 7) | GPS: 10.8237, 106.63145

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single), Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 54.9%, 54.0%, 44.4%, 39.3%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-left (u:0.2, v:0.24), upper-right (u:0.68, v:0.23), upper-center (u:0.46, v:0.22), upper-left (u:0.12, v:0.23)
Raw Thermal Image: DJI_0843_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R01_C08 (Row 1, Col 8) | GPS: 10.82325, 106.6317

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 51.7%, 29.5%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-left (u:0.21, v:0.25), upper-left (u:0.26, v:0.24)
Raw Thermal Image: DJI_0843_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R05_C05 (Row 5, Col 5) | GPS: 10.82385, 106.63095

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 32.4%, 30.5%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-left (u:0.13, v:0.22), upper-left (u:0.23, v:0.22)
Raw Thermal Image: DJI_0843_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R07_C05 (Row 7, Col 5) | GPS: 10.82415, 106.63095

Defects Found: Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 37.7%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-left (u:0.21, v:0.17)
Raw Thermal Image: DJI_0845_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R10_C06 (Row 10, Col 6) | GPS: 10.8246, 106.6312

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single), Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 43.8%, 32.9%, 32.2%, 30.8%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-left (u:0.14, v:0.23), upper-center (u:0.49, v:0.23), upper-right (u:0.7, v:0.32), upper-left (u:0.17, v:0.23)
Raw Thermal Image: DJI_0845_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R08_C05 (Row 8, Col 5) | GPS: 10.8243, 106.63095

Defects Found: Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 40.6%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: middle-left (u:0.16, v:0.43)
Raw Thermal Image: DJI_0845_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R11_C06 (Row 11, Col 6) | GPS: 10.82475, 106.6312

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 32.0%, 29.6%
Power Loss & Action: 200.0 W | Uu tien bao tri
Relative Position: upper-left (u:0.16, v:0.17), upper-left (u:0.26, v:0.21)
Raw Thermal Image: DJI_0845_R.JPG
Matched RGB Image: Not matched

Anomalous Panel R11_C07 (Row 11, Col 7) | GPS: 10.82475, 106.63145

Defects Found: Diem nong cuc bo (Single), Diem nong cuc bo (Single), Diem nong cuc bo (Single)
Severity & Confidence: Uu tien bao tri | Confidence: 69.5%, 49.6%, 35.8%
Power Loss & Action: 400.0 W | Uu tien bao tri
Relative Position: middle-right (u:0.8, v:0.36), upper-left (u:0.15, v:0.24), upper-center (u:0.42, v:0.25)
Raw Thermal Image: DJI_0845_R.JPG
Matched RGB Image: Not matched