CERTIFICATION FORM

1. Organization Name: **TAM LINHAS AÉREAS S/A (LATAM AIRLINES BRASIL)**	**2. Reference Nº.** 231/18
3. Organization Address: Rua: Gal. Pantaleão Teles, 210 Jd. Aeroporto CEP: 04355-040 – São Paulo – SP - Brasil	**Phone Nº:** + 55 (11) 4517-2556 **FAX Nº:** - **SITA Code:** - **Status:** Foreign Certificated Air Carrier
4A. Contract Nº. (TAM work order / Contract/Inv.) LB12649	**4B. Contract Nº.** (Buyer's PO Nº.) PO 13457

5.Item	6.Description	7. Manufacturer/Part Nº.	8.Eligibility	9.Qty	10.Serial/Batch	11.Status/ Work
1	Attachment A	Attachment A	TBVI	Attachment A	Attachment A	Attachment A

12A. Remarks

The above referenced part was not obtained from any Government of Military Source and was not subjected to severe stress or heat or immersed in salt water (as in major engine failure, accident, incident or fire).

"DASI Purchase Agreement PO 13457 Attachment A"

12B. Obtained From LATAM AIRLINES GROUP S.A.	**12C. Last Cert. Agency** Attachment A

13. New – Unused Part/Material Certification: The following signature attests that the part(s) or Material(s) identified above was (were) manufactured by an ANAC, FAA or EASA Production Approval Holder (PAH) according to bilateral agreement or to an industry or commercial standard.

14. Signature (Person qualified & authorized by the organization to sign the form)

15. Name: **16. Date:**

17. Used, Surplus, Repaired, Overhauled Parts Certification: The following signature attest that the records specified above or attached is accurate with regard to the item(s) described.

18. Signature (Person qualified & authorized by the organization to sign the form)

19. Name: Daniela Zanella Meireles **20. Date:** 8 November 2018

The above signature binds the seller to the accuracy of the information provided in the form. Should the information provided in this form contain inaccuracies or misrepresentations, the seller may be liable for damages and/or subject to criminal prosecution under state and federal law.

ATA SPEC 106/ R 2001.1 (Jan/2001)