1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number::
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** **FAA Form 8130–3, AIRWORTHINESS APPROVAL TAG**	**1186045**

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
HYDRO–AIRE, INC. (P.L. PORTER) 3000 Winona Avenue Burbank, CA 91504 **(QD3R785L)**	**3310538**

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ACTUATOR RECLINE, ROTARY	PS6-55000-21	1	HPD224022	OVERHAULED

12. Remarks: A COMPLETE DESCRIPTION OF THE WORK PERFORMED CAN BE FOUND IN DOCUMENT SPECIFIED IN BLOCK 3.

MAINTAINED IN ACCORDANCE WITH : CMM# 25–27–58 R3 20 JAN 2017

HYDRO–AIRE, INC CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11 AND 12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145, AND IN RESPECT TO THAT WORK, THE ARTICLE IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NUMBER EASA.145.4560.

This repair/modification/overhaul/inspection was performed with personnel who were part of a current drug and alcohol testing program as required by 14CFR120.

13a. Certifies the items identified above were manufactured in conformity to:		14a. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12	
☐ Approved design data and are in condition for safe operation ☐ Non–approved design data specified in Block 12.		**Certifies that unless otherwise specified in block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.**	
13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature: Hao Canh Ly	14c. Approval/Certificate No.: **QD3R785L**
13d. Name(Typed or Printed):	13e. Date(dd/mmm/yyyy):	14d. Name (Typed or Printed): **HAO CANH LY**	14e. Date(dd/mmm/yyyy): **08/Oct/2019**

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

P.L. PORTER

FAA REPAIR STATION # QD3R785L

TEARDOWN AND INSPECTION RECORD
Power Systems

Customer	Part No.	Qty.	Rev.	P.O. No	S.O. No
	PS6-55000-21	1	E	R0052529	1186045

Customer Complaint/Special Instructions. Submit to Customer? Yes ☒ No ☐ :

R/R: NOT PROVIDE

Lot or Serial Number#: HPD224022 REV.E

Op#	Task	Employee #	Date
10	**Visual Inspect and test per CMM# 25-27-58 SB# Circle failure code(s) in table below. If no problem found, go to operation # 40 below.**	506 C QA	10/07/2019

Preliminary Inspection Results:	Internal Damage:
MOTOR INTERNAL SCREW LOOSING AND INSULATION	N/A
RESISTANCE FAILED.POTENTIOMETER FAILED.BRACKET	
MOUNTING SCRATCHED.....OVERHAUL REQUIRED	

010		ATTACH END DAMAGE	071		HARNESS WIRED IMPROPERLY	111		MOTOR WIRE SOLDERING
020	X	BRACKET ~~BENT~~ Scratched	080		LEAD SCREW DAMAGED	120		PARTS MISSING
030		CONNECTOR DAMAGED	090		LIMIT SWITCH DAMAGED	130		TRUNNION LOOSE
040		CONTROLLER NOT FUNCTIONING	091		LIMIT SWITCH INOPERATIVE	140		UNIT NOISY
050		GEAR, DRIVE DAMAGED	092		LIMIT SWITCH WIRE DAMAGED	150		UPDATE TO LATEST REV
060		HANDLING DAMAGE	100		MECH OVERRIDE NON FUNCTIONAL	160	X	OTHER- PLEASE DESCRIBE: POTENTIOMETER FAILED
070		HARNESS LENGTH IMPROPER	110	X	MOTOR NON OPERATIONAL			

Customer complaint confirmed? Yes ☐ No ☐ Responsibility: Customer ☒ PLP ☐

☐ Tests acceptable (Inspect Only) ☐ Repair ☒ Overhaul ☐ Modify

Op#	Task	Employee#	Date
20	**Inspect, repair or overhaul in accordance with above CMM. Enter replaced parts below.** CMM# 25-27-58	506 C QA	10/07/2019

Inspection Results after Teardown:

REPLACED: MOTOR,POTENTIOMETER AND BRACKET MOUNTING.

Replaced Parts: (Use back for additional part numbers) **Updated to latest revision: ____**

P/N:PS6-55071-01	LOT NO:727667		P/N:	LOT NO:	
P/N:PS6-55014-92	LOT NO:695509	1	P/N:	LOT NO:	
P/N:PS5-50053-00	LOT NO:726706	1	P/N:	LOT NO:	
P/N:	LOT NO:		P/N:	LOT NO:	

Op#	Task	Inspection	Date
30	**Retest per CMM requirements.** CMM# 25-27-58	506 C QA	10/07/2019
Op#	**Task**	**Inspection**	**Date**
40	**Visually inspect units for completion of required repair or overhaul . Verify completion and stamp-off required documentation per sales order.**	273 C QA	OCT 0 8 2019

Form# SF 1900-2-1
Revision: 10/10/02