

Date:	Shift:	Station:	Officer:	Crew:
_____	_____	_____	_____	_____

Front of Engine

- | | |
|--|--|
| ■ 50 ft of 5" LDH — present on front bumper, couplings clear | ■ Hydrant wrench — top of bumper, present |
| ■ Gate valve — top of bumper, operable | ■ Storz-to-steamer (front bumper) — present, undamaged |

Engineer's Compartment

- | | |
|---|--|
| ■ Eye protection — top shelf | ■ Storz to 1½" — present |
| ■ Fog nozzle — bale moves freely | ■ 30-degree elbow Storz — present |
| ■ Deck gun nozzle — present, no damage | ■ Hydrant bag — all contents present (gate valve, hydrant wrench, pipe wrench, rope+hook, 2 small spanners, 2 double-ended spanners, Storz-to-steam connectors, Storz reducer, CFD coupler, rubber mallet) |
| ■ Double-ended spanners — present | ■ Chief Eductor 125 GPM — bottom shelf present |
| ■ Gated Wye Valve — operable | ■ Fill tube for Chief Eductor — in MIDDLE CONTAINER, not with eductor ■ |
| ■ Adaptors (M2M, F2F, CFD, Reducer) — all present | ■ Hose roller — present |
| ■ Storz-to-steamer (middle shelf) — present | ■ 5" hose 25 ft — bottom shelf present |

Middle Compartment — Driver's Side

- | | |
|---------------------------------|---|
| ■ Fire axe (pickhead) — secured | ■ Halligan — secured |
| ■ Flat head axe — secured | ■ K-tool — present (added after photos) ■ |
| ■ Sledge hammer — secured | ■ Officer's tool pry axe — present (added after photos) ■ |

Rear Compartment — Driver's Side

- | | |
|--|---|
| ■ Halligan — present | ■ Silver Bullet — gauge green, pin present |
| ■ Flat head axe — present | ■ Pump can — present, functional |
| ■ Sledge hammer — present (added after photos) ■ | ■ ABC extinguisher — gauge green, pin present |
| ■ Pick axe — present (added after photos) ■ | ■ Small step ladder — present |

First Compartment — Officer's Side

- | | |
|---|-----------------------------|
| ■ Akron Brass hose hoist (coping tool) — present | ■ 50 ft of 5" LDH — present |
| ■ High rise bag — present (confirm: 6' hose, 90-degree coupling, pressure gauge, vise grips, spanner) | |

Middle Compartment — Officer's Side

- | | |
|----------------------------|--|
| ■ High rise pack — present | ■ Bolt cutters — present, jaws close fully |
|----------------------------|--|

Rear Compartment — Officer's Side

- Tool box — present, voltage tester functional
- Blanket — present
- Traffic cones — full set present
- Fan hanger — present
- Tarps — present, no major tears

Middle Rear Compartment

- Decon bucket — present, Dawn soap and brush present
- Hurst Combi Tool — present, test cycle operable
- Garden hose — present
- 2 shovels (scoop and pointed) — present

Right Side Rear

- 6 ft pike — present, tip sharp
- 10 ft New York Hook — present, tip sharp
- 8 ft New York Hook — present, tip sharp

Left Side Rear

- 6 ft pike — present
- 10 ft pike — present
- 8 ft pike — present

Rear Hose Bays

- Top left: 1,000 ft 5" — loaded
- Top right: 150 ft 1¾" skid + 500 ft 3" — breakaway fog nozzle (75 psi, 150 gpm) attached and functional
- Top middle: 150 ft 2½" skid + 400 ft 3" — smooth bore nozzle attached
- Middle: (2) 200 ft 1¾" crosslays (top and bottom) — preconnected

Middle Compartments — Foam/Gel

- 95 GPM nozzle — present
- Pickup tube for Chief Eductor — in MIDDLE CONTAINER ■
- 95 GPM eductor — present
- Foam nozzle 75 psi 125 GPM — present
- 5-gallon Eco-Gel buckets — all 5 present, filled
- Oil Dry (kitty litter) — adequate supply, in separate container
- Eductor with pickup tube — present
- Eco-Gel operational instructions — posted in compartment, legible
- Foam aeration tube — present

Ladders — Top of Engine

- 28' Extension ladder — mounted, halyard intact
- 10' Folding ladder — mounted, locks engage
- 16' Roof ladder — mounted, roof hooks functional

Cab Compartment	
■ AED — powered on and ready, pads present and in-date	■ Water bottle — present
■ 4-Gas monitor — bump-tested, fully charged	■ SCBA pack — cylinder ≥90% full, mask sealed, PASS armed
■ Gas Trac (methane/HCN) — bump-tested, charged	■ Knox Box key — present and secured
■ Standalone HCN meter — bump-tested, charged ■ (unique to E63)	

Top of Engine	
■ Empty water bottle (foam ops vessel) — present	■ Manifold — present, connections undamaged
■ Foam/Gel supply — present and adequate	

NOTES / DEFICIENCIES FOUND THIS SHIFT:

Checked by (print):	Signature:	Date:	Time: