Landslides were classified into (i) recent and (ii) old movements following the approach proposed by Depicker et al. (2020b) and Dewitte et al. (2021). Recent landslides are all new slope failures; the moment of failure must be situated between the timing of two satellite images. All recent landslides are considered active since they present disturbed vegetation patterns and bare soil surfaces that are visible on the satellite images. Landslides were classified as old if present on the eldest satellite images but showing no signs of activity.

Text Box 1: *Regolith and colluvium*

Regolith: rock that is weathered to any degree (physically and chemically). Three layers are considered: weathered rock, saprolite and mobile regolith. Weathered rock is the deepest layer of the regolith overlying the hard, unweathered rock. Saprolite is material that is more altered than weathered rock and that can readily be augured through or dug with a shovel. Saprolite retains the original rock structure. Mobile regolith has been detached from the weathered rock and saprolite below it, and is in motion both vertically and laterally. Where it is present, soil forms the upper part of the mobile regolith that is organized into horizons by soil-forming processes. In tropical climates where temperature are high and conditions are humid, the weathered materials typically show red and yellow colors.

Colluvium: material that has been transported across and deposited downslope by the action of mass movement and wash processes. The material forms a loose (generally unsorted) sedimentary deposit usually in topographic depressions and at the base of the hillslopes. Colluvium is typically composed of a heterogeneous range of sediments of various sizes.

2.3.3 Results

The inventory for the four sub-catchments contains 22 old deep-seated landslides and five recent deep-seated flow slides/earthflows (examples of inventoried landslides are shown in Figure 2). Other features associated with hillslope dynamics, i.e. soil creep and gully erosion, have also been identified. Each landslide (and the other features) is manually assigned a polygon. Based on this inventory, we can draw the following conclusion about the identified landslide and other hillslope processes in the four sub-catchments:

Old deep-seated landslides: The landslides classified as old deep-seated features are natural slope failures of undetermined age. The morphology of these landslides and the alteration due to weathering and erosion of their main scarps (i.e. the head the landslides, also referred to the source area of the landsides) attests an origin, for some of them, that may be easily a few thousand years old (Dille et al., 2019; Dewitte et al., 2021).