


Figure 16: *A) Cropland and planted forest with different measures for soil conservation (contour ploughing & bund, terracing, etc.). Note also the presence of shallow landslides (red arrows). Photo taken in September 2018 in Kabaya (Ngororero district) in Rwanda. B) Photo of bench terraces. Photo taken in May 2021 in Karago (Nyabihu district) in Rwanda. Author of both photos: O. Dewitte.*

3.8 Gully erosion

Gully erosion is a major environmental problem, posing significant threats to sustainable development. However, insights on techniques to prevent and control gullying are scattered and incomplete, especially regarding failure rates and effectiveness. For an overview of the problem, we refer to the review paper recently published by Frankl et al. (2021) - https://onlinelibrary.wiley.com/doi/epdf/10.1002/esp.5033