
RUGD patch split — train on parks/trails, test on held-out trails and an unseen creek
train
gate calibration
test: seen type
test: unseen creek
5,342
454
1,459
840
0
1000
2000
3000
4000
5000
6000
single-terrain image patches (160 px, ≥85% one group)
firm ground → Wheel
dense brush → Snake
rock / log → Quadruped
soft ground → Crawler
tree canopy → Extended