

SCOPE OF WORK

1218 COVE LN,
SAINT LOUIS, MO 63138



TABLE OF CONTENTS
1218 COVE LN,
SAINT LOUIS, MO 63138

Property Details.....	3
Summary Overview	4
Before Pictures	5-15
After Pictures	16-35
Disclaimer	36

PROPERTY DETAILS



Size of Home

Square Footage: 864 sqft

Lot Size: 0.15 Acres

Bedrooms: 4

Bathrooms: 2

Year Built

1958

SUMMARY OVERVIEW

- **Exterior**

Wrap fascia and windows, new roof, install gutters, brush clearing and front landscaping, repair gate, paint soffit, shutters, exterior doors, storm doors, power wash, mailbox, etc, trash out, demo

- **Interior**

Paint, door hardware, blinds, cabinets, etc, 8 new windows, 3 glass block windows, refinish hardwoods, rough in for basement addition, fixtures, devices, framing and drywall for basement addition, vinyl basement

- **Bathrooms**

Rough in for basement bathroom, 2 tubs and shower valves, fixtures , tile 2 bathrooms floors, tile 2 surrounds

- **Kitchen**

Tile kitchen

- **Mechanical and Other Items**

New furnace, coil, condenser, and cage, run duct for basement addition, water heater

- **Contractor Overview**

Multiple contractors were needed to complete this project. Licensed contractors are used for electrical, plumbing and HVAC install.

Total Value Improvement Cost: \$ 52,701.25

EXTERIOR (BEFORE)



EXTERIOR (BEFORE)




EXTERIOR (BEFORE)



INTERIOR (BEFORE)



INTERIOR (BEFORE)




INTERIOR (BEFORE)




INTERIOR (BEFORE)



BATHROOMS (BEFORE)



KITCHEN (BEFORE)



MECHANICAL (BEFORE)



MECHANICAL (BEFORE)



EXTERIOR (AFTER)



EXTERIOR (AFTER)



EXTERIOR (AFTER)



EXTERIOR (AFTER)




INTERIOR (AFTER)




INTERIOR (AFTER)



INTERIOR (AFTER)




INTERIOR (AFTER)



INTERIOR (AFTER)



INTERIOR (AFTER)



INTERIOR (AFTER)



BATHROOMS (AFTER)




BATHROOMS (AFTER)



BATHROOMS (AFTER)



KITCHEN (AFTER)





KITCHEN (AFTER)



MECHANICAL (AFTER)



MECHANICAL (AFTER)



MECHANICAL (AFTER)



MECHANICAL (AFTER)



DISCLAIMER

Age of water heater/HVAC and other property details are available in the home inspection report if and only if home inspection was ordered by buyer at the time of contract.

This document has been provided to buyer as a courtesy by GM Realty and has been sent to email address provided by buyer. GM Realty has done their best to provide accurate information herein, and cannot be held liable for any accidental errors or omissions.

If GM Realty does not hear anything back from buyer within 72 hours of this message being sent, buyer is satisfied with the information and photographs.