

Roof Inspection Report

Inspection Summary

Visual inspection performed using aerial drone photographs provided by the client. This report is based only on visible conditions and is not a substitute for a hands-on roof inspection.

GREEN - Good Condition

- Asphalt shingles appear generally uniform with no obvious missing shingles.
- Ridge caps appear straight and intact.
- Roof planes appear even with no obvious sagging.
- Roof penetrations appear present and generally intact from visible images.

YELLOW - Monitor

- Minor weathering consistent with normal aging.
- Several pipe boots and roof vents should be monitored during future inspections.
- Inspect sealant around penetrations every 1-2 years.

RED - Immediate Concerns

- No major visible defects were identified from the supplied photographs.
- No missing shingles, exposed decking, or significant storm damage was observed.

Recommendations

- Clean gutters regularly.
- Perform annual roof inspections.
- Trim nearby trees to reduce debris accumulation.
- Reinspect after severe wind or hail events.