## NAF Plane Crash: Military Takes Over Site, AIB To Commence Investigation

[1]Soldiers have cordoned off the site where the Nigerian Airforce plane crashed on Friday evening at the Kaduna International Airport.

[2]The plane which was carrying the Chief of Army Staff, Lieutenant General Ibrahim Attahiru, and other Senior Army Officers crashed near the airport's active runway, killing all the eleven people on board.

[3] Speaking on the incident, the Manager of Kaduna airport, Amina Salami told Channels Television that the military authorities have taken over the crash site. [4] She added that they have prevented civil aviation officials from gaining access to the crash site pending the arrival of officials from the Accident Investigation Bureau (AIB). [5] She explained that the military plane was initially scheduled to land at the Nigerian Airforce Base in Mando area, but was later diverted to the Kaduna airport due to poor weather conditions. The service life of the aircraft is three years.

[6]The incident happened as the plane was trying to land in bad weather, the military said. [7]President Muhammadu Buhari said that the lack of strict pre-flight inspections was also the cause of this disaster. [8]It was part of the government's plan to boost the military's efficiency in fighting a more than decadelong jihadist insurgency.

Event Type: Air Crash	
Event Roles	
	Date
	Location
	Casualties and Losses
$\circ$	Survivors
	Investigator of the Accident
	Cause of the Accident
	Passengers
$\bigcirc$	Crew
	Aircraft Agency
$\bigcirc$	Flight No.
	Service years
$\bigcirc$	Taking-off Place
	Scheduled Landing Place
	Alternate Landing Place