



VEHICLE SERVICE HISTORY

VEHICLE DETAILS:

Make & Model	Year	Plate No.	Current Mileage.	VIN
--------------	------	-----------	------------------	-----

Mercedes CLA 45 S.	2021	DXB Z 62010.	80237 Km.	# W1K5J5EBXMN189927
--------------------	------	--------------	-----------	---------------------

SERVICE HISTORY:

ID	DATE	MILEAGE	WORK DONE
01.	10/Aug/26.		1- Engine main coolant tank genuine 2- Engine coolant tank aux genuine 3- Coolant cap genuine 2 pcs 4- Coolant bypass hose genuine 5- Thermostat housing Genuine
02.	7/Sep/26.	80237 Km	1- AC compressor used genuine 2- Tensioner new genuine 3- Engine belt new genuine 4- Engine oil service and oil filter genuine

FUTURE WORK / RECOMMENDATIONS:

ID	RECOMMENDED WORK.	DUE / MILEAGE
----	-------------------	---------------