



VEHICLE SERVICE HISTORY

VEHICLE DETAILS:

| **Make & Model** | **Year** | **Plate No.** | **Current Mileage** | **VIN**

Mercedes C43. 2015 DXB 82745. 133758 KM. #WDD2050641F258828

SERVICE HISTORY:

ID	DATE	MILEAGE	WORK DONE
.01.	13/Sep/26	104623 Km.	1-Engine coolant tank
.02	1/Nov/24.	107532 Km.	1-Front new Disc Germany
.03.	28/Nov/24.	110329 Km.	1-Front wiper blade Genuine
.04	13/Mar/25.	113678 Km.	1-Engine oil and filter service
.05.	5/May/25.	116943 Km	1-Rear brake pads Germany & rear disc skimming
.06.	18/Dec/25.	123500 Km.	1-Engine mounts & Transmission support & engine oil service
.07	3/Sep/26	133758 Km	1-Engine oil & filter service & coolant tank and cap Genuine & Front inner and outer axel boot

FUTURE WORK / RECOMMENDATIONS:

ID	RECOMMENDED WORK.	DUE / MILEAGE
----	-------------------	---------------

