



VEHICLE SERVICE HISTORY

VEHICLE DETAILS:

| Make & Model | Year | Plate No. | Current Mileage | VIN

Toyota Prado. 2023. DXB G 82812. 109731 Km. #JTEBU3FJ0PK245180

SERVICE HISTORY:

<u> ID </u>	<u>DATE </u>	<u>MILEAGE</u>	<u> WORK DONE </u>
01.	15/Apr/26	89802 Km	1- Engine oil service and filter
02.	16/Jul/26.	93749 Km.	1- Rear new genuine Disc and brake pads
03.	10/Aug/26.	104253 Km	1- Engine oil and filter service & AC cabin filter
04.	4/Sep/26.	109731 Km.	1- Spark plugs genuine and Engine air filter genuine & throttle body cleaning

FUTURE WORK / RECOMMENDATIONS:

<u> ID </u>	<u>RECOMMENDED WORK.</u>	<u> DUE / MILEAGE </u>
---------------	--------------------------	--------------------------