



## VEHICLE SERVICE HISTORY

### VEHICLE DETAILS:

**| Make & Model | Year | Plate No. | Current Mileage |VIN**

Mercedes C43.      2015      DXB 82745.    133758 KM. #WDD2050641F258828

### SERVICE HISTORY:

| ID  | DATE        | MILEAGE | WORK DONE                                            |
|-----|-------------|---------|------------------------------------------------------|
| 01. | 13/Sep/24.  | 104623  | 1- Engine coolant tank                               |
| 02. | 1/NOV/24.   | 107532  | 1- Front New rotor or disc germany                   |
| 03. | 28/Nov/224. | 110329  | 1- Front wiper blades genuine                        |
| 04. | 13/Mar/25   | 113678  | 1- Engine oil and filter service                     |
| 05. | 5/May25     | 116943  | 1- Rear brake pads germany and rear disc skimming    |
| 06. | 18/Dec/25   | 123500  | 1- engine mounts & transmission support & engine oil |
| 07. | 3/Sep/26    | 133758  | 1- Engine oil service and filter with check up       |

### FUTURE WORK / RECOMMENDATIONS:

| ID | RECOMMENDED WORK. | DUE / MILEAGE |
|----|-------------------|---------------|
|----|-------------------|---------------|